



Cellar Conversion Battersea



We were the second company to tackle this cellar conversion in an old Victorian building in Battersea in 1998

The first had applied a 'bonded waterproof render and screed' tanking system which had failed due to (predictable) structural movement and used that as an excuse to wriggle out of any guarantee liability.

When we started out work there was about 4" (100mm) of water on the floor.

All the internal finishes were removed and an underfloor perimeter channelling system (Waterguard) was installed together with two perforated sump liners, each with a mains powered pump and battery back-up pump. The two sumps are underneath the wood lined step in the left of the picture and all the pipes and wires were concealed behind the wall lining at a low level.

Having returned to the property on an annual basis to carry out pump servicing over the years, this beautiful basement is as dry now as the day we left it.

Phone us FREE on 0800 413 801 (Call charges normally apply to mobiles)

E-mail us at advancedbasementsolutionsltd@gmail.com